




Electromagnets

need a coil of wire and an electric current

make it stronger by ...

- increasing the current
- increasing the number of turns of wire
- using an iron core*

*steel would become permanently magnetized



S

Do the Qs on P195

Hand in on Friday morning.